

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

PROMONTORY ROUTE RAILROAD TRESTLES, S.P. TRESTLE                      HAER UT-64-H  
779.91  
(Trestle #1)  
Golden Spike National Historic Site  
One mile southwest of junction of State Highway 83 and Blue Creek  
Corinne vicinity  
Box Elder County  
Utah

## INDEX TO BLACK AND WHITE PHOTOGRAPHS

Kristi Hager, photographer, August 2004

UT-64-H-1	Trestles #2 and #1 (center), long view from Central Pacific Railroad grade. Note Adams Ranch (right). View to north
UT-64-H-2	Trestle # 1. View to northwest
UT-64-H-3	Trestle #1 (right) and Trestle #2 (left). View to west
UT-64-H-4	Trestle #1 (right) and Trestle #2 (left). View to north-northwest
UT-64-H-5	Decks of Trestle #1 (foreground) and Trestle #2. View to southwest
UT-64-H-6	Decks of Trestle #2 (foreground) and Trestle #1. Note Adams Ranch and Thiokol (upper right). View to northeast
UT-64-H-7	Trestle #1, deck from above. View to southwest
UT-64-H-8	Trestle #1, deck from above. Note Adams Ranch and Thiokol (upper right). View to northeast
UT-64-H-9	Trestle #1, deck from below. View to southwest
UT-64-H-10	Trestle #1, southeast elevation from across wash. View to northwest
UT-64-H-11	Trestle #1, southeast elevation. View to northwest
UT-64-H-12	Trestle #1, northwest elevation. View to southeast

PROMONTORY ROUTE RAILROAD TRESTLES, S.P.

HAER UT-64-H

INDEX TO PHOTOGRAPHS

Page 2

UT-64-H-13	Trestle #1, three quarters view. View to west
UT-64-H-14	Trestle #1, three quarters view. View to north
UT-64-H-15	Trestle #1, three quarters view. View to east
UT-64-H-16	Trestle #1, three quarters view. View to south
UT-64-H-17	Trestle #1, diversion wall (left). View to east
UT-64-H-18	Trestle #1, diversion wall. View to west
UT-64-H-19	Trestle #1, diversion wall. View to north
UT-64-H-20	Trestle #1, southwest abutment and wing wall. View to west
UT-64-H-21	Trestle #1, detail of southwest abutment lower sill and gabion baskets. View to west
UT-64-H-22	Trestle #1, detail of southwest abutment upper timbers and gabion basket. View to west
UT-64-H-23	Trestle #1, detail of southwest abutment and deck. View to south
UT-64-H-24	Trestle #1, northeast abutment and wing walls. View to north
UT-64-H-25	Trestle #1, wing wall on northwest side of northeast abutment. View to northeast
UT-64-H-26	Trestle #1, detail of bolt and washer on wing wall on north west side of northeast abutment. View to northeast
UT-64-H-27	Trestle #1, detail of connecting bolts and spikes on northeast abutment vertical support timbers. View to east
UT-64-H-28	Trestle #1, detail of connecting bolts and spikes on upper northeast abutment. View to east
UT-64-H-29	Trestle #1, detail of bolts on northeast abutment lower vertical support timbers. View to north
UT-64-H-30	Trestle #1, detail of stringers and spacers on northeast end of deck. View to southwest
UT-64-H-31	Trestle #1, detail of spacer, bolt, and spikes on northeast end of deck. View to southwest
UT-64-H-32	Trestle #1, detail of spacer and bolt assembly with tie and guard timber, southwest end of deck. View to east-northeast